


## **Manufacturing Notice**

Name:	<b>Plating New Installation Rims</b>
-------	--------------------------------------

To:	<b>Plating Vendor</b>
-----	-----------------------

Affected Parts:	<b>All two piece "New Installation" Custom Cupholder Company top appearance rims.</b>
Part Name:	<b>Top Appearance Rim</b>


Notice:	<p style="text-align: center;"><b><u>IMPORTANT PLATING INFORMATION</u></b></p>  <p style="text-align: center;">X-SECTION OF RIM SHOWN</p> <p style="text-align: center;">RIM</p> <p>MAXIMUM PLATING THICKNESS ON INSIDE OF RIM FLANGE TO BE NO MORE THAN .004". REMOVE ANY LOCALIZED BUILDUP OR POOLING OF PLATING FINISH.</p>
---------	--

## Manufacturing Notice

Name:	Plating New Installation Bottom Cups
-------	--------------------------------------

To:	Plating Vendor
-----	----------------

Affected Parts:	All two piece "New Installation" Custom Cupholder Company bottom cups.
Part Name:	Bottom Cup

Notice:	<p style="text-align: center;"><b><u>IMPORTANT PLATING INFORMATION</u></b></p> <p style="text-align: center;">MAXIMUM PLATING THICKNESS ON OUTSIDE TOP EDGE OF CUP TO BE NO MORE THAN .004". REMOVE ANY LOCALIZED BUILDUP OR POOLING OF THE PLATING FINISH.</p>  <p style="text-align: center;">X-SECTION OF CUP SHOWN</p>
---------	--